United States of America

Department of Transportation—Federal Aviation Administration

Supplemental Type Certificate

Number SA4244SW

This certificate, issued to S-TEC Corporation Rt. 4, Bldg. 946

Wolters Industrial Complex

Mineral Wells, Texas 76067

certifies that the change in the type design for the following product with the limitations and conditions

therefor as specified hereon meets the airworthiness requirements of Part 3 of the Civil Air

Regulations.

Original Product - Trype Certificate Number: 3A12

Make: Cessna

Model: 172N. 172P

Description of Type Design Change: Installation of S-TEC System 60 Single Axis Flight Guidance System, Model ST-012, according to Bulletin No. 112, Revision 2, dated 8-10-81 and Master Drawing List No. 9225, Revision B, dated 8-10-81, or later FAA approved revision. (28 Volt System)

Limitations and Conditions: See Continuation Sheet, page 2 of this STC.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: November 3, 1980

Sale ressued: 3/6/81; 9/18/81

Revision 2

Date of issuance:

December 11, 1980

Tale umended:

By direction of the Administrator

(Signature) Don P. Watson

Chief, Engineering and Manufacturing Branch

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

United States of America

Department of Transportation—federal Aviation Administration

Supplemental Type Certificate

(Continuation Sheet)

Number SA4244SW

Revision 2

Limitations and Conditions:

1. FAA Approved Supplemental Flight Manual P/N 8922, dated 12-11-80 is required for Cessna Model 172N

or

FAA Approved Supplemental Flight Manual P/N 8922-1 dated March 6, 1981, is required for Cessna Model 172N, S/N 17271034 and BELOW.

- 2. Pilot's Operating Handbook and FAA Approved Airplane Flight Manual Supplement P/N 8942 dated March 6, 1981, is required for Cessna Model 172N, S/N 17271035 and UP and Cessna Model 172P.
- 3. Compatibility of this modification with other previously approved modifications must be determined by the installer.